
LIFE SAFETY SYSTEMS, INC.

P.O. Box 76, Essex Jct., VT 05453-0076



PHONE 802-879-5355 IN VERMONT 1-800-649-9995 FAX 802-879-4574

FIRE ALARM SYSTEM Test & Inspection Report

AMENDED 7.8.13

VERMONT PROOF OF INSPECTION STICKER # 13-01959 SYSTEM IDENTIFICATION # F-27417

Customer: Champlain Apartments – 355 Pearl St.

Date: April 11, 2013

Contact: Gene Richards

Location: 355 Pearl St.,

Burlington

Time: Start: 2:50 End: 4:40 Total: 1:50

Techs Sent: MF, MC

Panel Make & Model: Silent Knight 5208

Date Installed: July 7, 2010

			DC Charge Rate			Battery Voltage	Under Load
(Ah)	ACL	ine De	C Cha	irge Ra	te	DC Starting	DC Ending
Power Supply (7)	122.5	5	28	3.0		26.9	25.0
Manual Pull Stations	Qty:	7	#	Zones:	3	Tested:	7
Signal Horn/Strobes	Qty:	4 : 3	. #	Zones:	2	Tested:	6
Apartment Horns	Qty:	16	#	Zones:	4	Tested:	16
AC Strobes	Qty:	H4 *	#	Zones:	N/A	Tested:	4
Exterior Horn/Strobes	Qty:	2	#	Zones:	1	Tested:	2
Automatic Detection	-						
Photoelectric Smokes	Qty:	4	#	Zones:	2	Tested:	4
CO Detectors	Qty:	1	#	Zones:	1	Tested:	1
AC Smoke/CO Combo Units	Qty:	55	#	Zones:	N/A	Tested:	55
Sprinkler Water Flow	Oty:	1	#	Zones:	1	Tested:	1
Sprinkler Tampers	Qty:	1	#	Zones:	1	Tested:	1
Notes: All smoke detectors test	ed are	cleaned.					
Auxiliary Features							
Sprinkler Bell	Qty:	1	#	Zones:		Tested:	1

Current Deficiencies

- 1) Apartment 1 AC smoke detectors not working ***Corrected 7/8/2013***
- 2) Apartment 2 AC smoke detectors not working ***Corrected 7/8/2013***

Deficiencies Corrected

1-2) None Corrected 7/8/2013

Comments: 1) Stairwell AC combo unit tandem with Apt 6. 2) Boiler Room AC combo tandem with Apt 1. 3) Apartment 6 AC smoke detectors don't respond to smoke. 4) Basement stair AC smoke detector doesn't respond to smoke. 5) Design approved by fire marshal when installed.

LIFE SAFETY SYSTEMS, INC.

P.O. Box 76, Essex Jct., VT 05453-0076

PHONE 802-879-5355

FAX 802-879-4574

IN VERMONT 1-800-649-9995

Authorized Representative VT State License #T1-5334

Reviewed by #T1-5334

cc: VT Department of Public Safety - Burlington Fire Department

Williston

Internal Notes

- 1. Apartment 2 entry at front of building
- 2. Apartment 6 entry in back of building.
- 3. All horn/strobes are in apartment 6.
- 4. Apartment 1 bedroom off kitchen.